

# NFRC Values

Series 600 Thermally Broken  
Multi-Slide Door



**western**  
window systems  
westernvolumeprogram.com

## Cardinal High-Performance Low-E

Unit Makeup ▶ 7/8" OA ▶ Stainless Steel Spacer ▶ 366/Argon Glass ▶ No Grids ▶ Medium Stile ▶ 1.81" Roller Assembly

	U-Value	SHGC	Visible Light	Condensation Resistance
Water Barrier Sill	0.37	0.23	0.51	42
Flush Sill	0.39	0.23	0.51	37

### AAMA Structural Ratings

Water Barrier Sill: LC-PG25

Flush Sill: N/A

